SGS ITALIA S.p.A.

Industrial

Via Caldera, 21 20153 Milano Tel. (02) 7393.1 Fax: (02) 70125067

Affiliate code 095103





Pagina 1 di 2 Page 1 of 2

## INSPECTION CERTIFICATE No.0031/MI

Data: 07/06/2019 FILE NO. 19.16267

**FORNITORE** 

LEGHORNGROUP SRL - VIA DEGLI ARROTINI 34/36 - LIVORNO

SUPPLIER

COSTRUTTORE MANUFACTURER LEGHORNGROUP SRL - VIA DEGLI ARROTINI 34/36 - LIVORNO

DESCRIZIONE MATERIALE MATERIAL DESCRIPTION

PRODOTTO SOTTOPOSTO ALL'ATTIVITA' **NEW FORKSEAL** DOCUMENTI DI IDENTIFICAZIONE: ISO 17712

ISPEZIONE ESEGUITA INSPECTION PERFORMED

EFFETTUAZIONE DELLE PROVE DI ANTIMANOMISSIONE DEL SIGILLO DI ALTA SICUREZZA NEW FORKSEAL PREVISTE DALLA NORMA ISO 17712:2013 punto 6)

**DOCUMENTI DI RIFERIMENTO** REFERENCE DOCUMENTS

Le prove effettuate sul materiale sono state eseguite in conformità con i seguenti documenti: Activities have been performed according to the following documents:

- NORMA ISO 17712:2013 punto 6)

- LEGHORNGROUP TEST REPORT NO. 0006-18.04.2019 finalized on 17/05/2019

SGS INSPECTION REPORT NO. 19.500.0290rev1 DATED 23/05/2019

RISULTATI

RESULTS

I risultati ottenuti dalle verifiche e dai collaudi effettuati sono riportati in dettaglio nei seguenti documenti: TEST RESULTS

The test results of the activities performed are detailed in the following documents

Per witness:

For witness

LEGHORNGROUP Rapporto di prova NO. 0006-18.04.2019 finalizzato il 17/05/2019



Member of SGS (Société Générale de Surveillance) Group

ty unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory ions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The nearly's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissi party's personnel or the analysis results

Member of the International Federation of Inspection Agencies Limited, London,

FT 06/12

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.



SGS ITALIA S.p.A.

Industrial Via Caldera, 21 20153 Milano

Tel. (02) 7393.1 Fax: (02) 70125067

Affiliate code 095103





CERTIFICATO D'ISPEZIONE No.0031/MI

INSPECTION CERTIFICATE No. 0031/MI Data: 07/06/2019

FILE NR. 19.16267

Pagina 2 di 2 Page 2 of 2

CONCLUSIONI CONCLUSIONS

Le prove di antimanomissione effettuate sono risultate, per le attività eseguite, conformi ai requisiti dei documenti di riferimento e in particolare alla norma ISO 17712:2013 punto: 6.

The appropriate testing activities have been performed and the results conform to the requirements outlined in ISO 17712:2013 Clause 6. SGS Italia S.p.A

On behalf of Business Manager

Mara Codognotto

Member of SGS (Société Générale de Surveillance) Group

Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.

FT 06/12

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

